

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

955
NNE
> 1
1.272 mi.
6715 ft.

H M PLUMBING
2232 MCDONALD AVE
BROOKLYN, NY

NY Spills S102961970
N/A

Relative:
Higher

Actual:
19 ft.

SPILLS:

Name: H M PLUMBING
Address: 2232 MCDONALD AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9710707 / 2005-11-09
Facility ID: 9710707
Facility Type: ER
DER Facility ID: 64160
Site ID: 67090
DEC Region: 2
Spill Cause: Unknown
Spill Class: C3
SWIS: 2401
Spill Date: 1997-12-19
Investigator: JGJONES
Referred To: Not reported
Reported to Dept: 1997-12-19
CID: 369
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1997-12-19
Spill Record Last Update: 2006-03-22
Spiller Name: ILENE
Spiller Company: H M PLUMBING
Spiller Address: 2232 MCDONALD AVE
Spiller Company: 001
Contact Name: ILENE - CB11
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL CALLED ILENE - CB11 - 12:30PM GREASE - GUYS ARE EMPTYING FROM CONSTRUCTION VEHICLES ONTO SIDEWALK. GOES ON ALL THE TIME. 4/12/04-Vought-Spill transferred from Tibbe to Rommel as per Rommel. 11/9/05- Jones- Called referring agency, no institutional memory of this event. Called HM Plumbing, no grease currently being put on sidewalk in vicinity. Closing spill."
Remarks: "caller had no further information at this time."

All Materials:

Site ID: 67090
Operable Unit ID: 1053606
Operable Unit: 01
Material ID: 328987
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Recovered: .00
Oxygenate: Not reported